



This is the filter section of the design. Input PWM waveform at top left, output to power amp at bottom left.

Suspect that the problem may be in C5 and C10. Both have long traces between themselves and the pins on the opamp, about 1" and 1.5" respectively!